

Software Release Identification

Date: March 28, 2008
Product: Mk.2 PerformanceWare
New Version: 4.17

Engineers: Nellie Kurtser
Part Number: 69-004-906-00
Old Version: 4.16

Application	New Version	Old Version
Mk2	4.17*	4.16
WinExVec	4.06	4.06
WinPlotVI	3.15	3.14
Mapping	4.06*	4.05

*changed in this release

Effectivity

All new Mk.2 shipments and paid software upgrades.

PerformanceWare is restricted from general distribution. Existing customers requiring software upgrades should receive the Mk.2 standard software (version 3.17 at this date) unless one of the following conditions is met.

1. The existing customer has previously purchased the PerformanceWare software package (their current software is at version 4.00 or higher).
2. The existing customer is specifically making a PerformanceWare purchase, such as an SE Upgrade.

Dependencies

Firmware version **2.40** or higher is required to allow the use of all the functionality available in Mk.2.

Explanation

Mapping Application

1. Correction of Oryx EX adapter conversion table

Mk2 Application

1. Check "DC supply recognized" firmware flag before test light on.
2. Add 8 KV / 12 KV waveform network testplans compliance.